

Vehicle details

VIN	MMCXNA03A NH002065	Brand	mitsubishi	Maintenance date	-
Licence Plate	N9-94-GF	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	06/10/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	93 507 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	05/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Hankook 165/65/14 Summer 5.0 mm



Hankook 165/65/14 Summer 5.0 mm



Hankook 165/65/14 Summer 7.0 mm

Hankook 165/65/14 Summer 7.0 mm

Exterior

1		Part	Bumper	2		Part	Wing
		Position	Front			Position	Front right
3		Damages	Scratched	4		Damages	Dented
		Severity	Length (cm) > 10			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Smart Repair
		Part	Exterior door mirror shell			Part	Door
		Position	Front right			Position	Front right
		Damages	Broken			Damages	Dent & Chips
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	Replace			Repair mode	Repair

5		PartWing PositionBack right DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	6		PartBumper PositionBack DamagesBroken SeverityLength (cm) > 10 Repair modeRepair
7		PartDoor PositionBack left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	8		PartDoor PositionFront left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair
9		PartStep plate PositionFront left DamagesDented Severity- Repair modeFor info			