

Vehicle details

VIN	MMCXNA03A NH004867	Brand	mitsubishi	Maintenance date	-
Licence Plate	N0-42-HL	Model	SPACE STAR 1.2 Cool+ SDA 5d	Maintenance mileage	-
Registration date	18/10/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	75 363 km	Engine size	1193	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Spare key	✓
Key	✓

Tyres

Pirelli 165/65/14 Summer 3.5 mm		Pirelli 165/65/14 Summer 3.0 mm	
Bridgestone 165/65/14 Summer 4.0 mm		Bridgestone 165/65/14 Summer 4.0 mm	

Exterior

1		Part	Bonnet	2		Part	Door
		Position	-			Position	Front right
3		Damages	Dented	4		Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair
		Part	Wing			Part	Bumper
		Position	Back right			Position	Back
		Damages	Dented			Damages	Broken
		Severity	Diameter (mm) > 20			Severity	Length (cm) > 10
		Repair mode	Smart Repair			Repair mode	Repair

5



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



Part	Door
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair