

Vehicle details

VIN	MMCXNA05A KH218758	Brand	mitsubishi	Maintenance date	01/01/1900
Licence Plate	J6-87-NF	Model	SPACE STAR 1.0 Cool+ 5d	Maintenance mileage	-
Registration date	24/09/2020	Year	2020	Exterior Color	Silver Metallic
Odometer	102 564 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	27/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Key	✓
Remote key	✓

Tyres

Vredestein 165/65/14 Summer 3.0 mm		Vredestein 165/65/14 Summer 3.0 mm	
Bridgestone 165/65/14 Summer 3.0 mm		Bridgestone 165/65/14 Summer 4.0 mm	

Exterior

1		Part	Bumper	2		Part	Bonnet
		Position	Front			Position	-
3		Damages	Dent & Chips	4		Damages	Dent & Chips
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair
						Part	Roof
		Position	Back right			Position	-
		Damages	Dented			Damages	Rusty
		Severity	Diameter (mm) > 20			Severity	-
		Repair mode	Repair			Repair mode	Lumpsum repair

5		Part	Bumper
		Position	Back
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Repair
6		Part	Wing
		Position	Front right
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Repair
8		Part	Door
		Position	Front right
		Damages	Dented
		Severity	Diameter (mm) > 20
		Repair mode	Smart Repair

Interior damage

7		Part	Fabric seat
		Position	Front left
		Damages	Burnt
		Severity	-
		Repair mode	Smart Repair

Comments

Opslagpark : Dekra Ayvens