


Vehicle details

VIN	MMCXNA05A LH024853	Brand	mitsubishi	Maintenance date	-
Licence Plate	K7-86-BH	Model	SPACE STAR 1.0 Cool+ 5d	Maintenance mileage	-
Registration date	18/11/2020	Year	2020	Exterior Color	White Solid
Odometer	50 592 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	07/08/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Manual air-conditioning	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Hankook 165/65/14 All seasons 6.0 mm		Hankook 165/65/14 All seasons 6.5 mm	
Hankook 165/65/14 All seasons 7.0 mm		Hankook 165/65/14 All seasons 7.0 mm	

Exterior

2		Part	Door	3		Part	Door
		Position	Front right			Position	Back right
4		Damages	Dented	5		Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

6



Part

Door

Position

Back left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

7



Part

Wing

Position

Front left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

Interior damage

1



Part

Fabric seat

Position

Front left

Damages

Burnt

Severity

-

Repair mode

Smart Repair