


Vehicle details

VIN	MMCXNA05A LH026126	Brand	mitsubishi	Maintenance date	-
Licence Plate	J3-60-SH	Model	SPACE STAR 1.0 Cool+ 5d	Maintenance mileage	-
Registration date	07/10/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	72 055 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	21/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Key	✓

Tyres

Continental 165/65/14 Summer 7.0 mm




Continental 165/65/14 Summer 6.5 mm



Bridgestone 165/65/14 Summer 6.0 mm



Bridgestone 165/65/14 Summer 6.0 mm



Exterior

1		Part	Bumper	2		Part	Wing
		Position	Front			Position	Front right
3		Damages	Scratched	4		Damages	Dented
		Severity	Length (cm) > 10			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Smart Repair
		Part	Door			Part	Door
		Position	Front right			Position	Back right
		Damages	Dented			Damages	Dented
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Smart Repair			Repair mode	Smart Repair

5



Part

Position

Damages

Severity

Repair mode

Wing

Back right

Dented

Diameter (mm) > 20

Smart Repair

●

●

6



Part

Position

Damages

Severity

Repair mode

Tailgate / Boot door

-

Dented

Diameter (mm) > 20

Smart Repair

●

●

7



Part

Position

Damages

Severity

Repair mode

Roof wind deflector

Back

Chemical deposit

-

Lumpsum repair

●

●

8



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Dented

Diameter (mm) > 20

Smart Repair

●

●

9



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dented

Diameter (mm) > 20

Smart Repair

●

●

10



Part

Position

Damages

Severity

Repair mode

Windscreen

-

Stone impact

-

For info

●

●