


Vehicle details

VIN	MMCXNA05A LH026132	Brand	mitsubishi	Maintenance date	-
Licence Plate	J9-02-ZR	Model	SPACE STAR 1.0 Cool+ 5d	Maintenance mileage	-
Registration date	11/11/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	66 425 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Remote key	✓
Spare key	✗

Tyres

165/65/14 All seasons 5.0 mm
Mastersteel



165/65/14 All seasons 4.5 mm
Mastersteel



165/65/14 All seasons 6.0 mm
Mastersteel

165/65/14 All seasons 6.0 mm
Mastersteel

Exterior

2



Part	Other bodywork
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	For info
Buitenkant voertuig	

3



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

4





Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5





Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

6





Part	Bumper
Position	Front
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7





Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace