


Vehicle details

VIN	NLHA851AA JZ394153	Brand	HYUNDAI	Maintenance date	-
Licence Plate	SR-77-5P	Model	I10 1.0i Blue ActieAuto 5d Comfort + navi HPL	Maintenance mileage	-
Registration date	31/05/2018	Year	2018	Exterior Color	Blue Solid
Odometer	90 891 km	Engine size	998	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Audio System	✓



Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 155/70/13 Summer 3.0 mm		Continental 155/70/13 Summer 7.0 mm	
Hankook 155/70/13 Summer 1.5 mm		Hankook 155/70/13 Summer 2.0 mm	

Exterior

1



Part	Bonnet
Position	-
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



Part	Bumper
Position	Front
Damages	Improper repair
Severity	-
Repair mode	Repair

3



Part	Wing
Position	Front left
Damages	Improper repair
Severity	-
Repair mode	Repair

4



Part	Door
Position	Front left
Damages	Improper repair
Severity	-
Repair mode	Repair

5



Part	Exterior door mirror shell
Position	Left
Damages	Improper repair
Severity	-
Repair mode	Repair

6



Part	Bumper
Position	Back
Damages	Improper repair
Severity	-
Repair mode	Repair

7



Part	Wing
Position	Back right
Damages	Improper repair
Severity	-
Repair mode	Repair

8



Part	Exterior door mirror shell
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair