

Vehicle details

VIN	NLHA851AA JZ406245	Brand	HYUNDAI	Maintenance date	-
Licence Plate	SL-55-2T	Model	I10 1.0i Blue ActieAuto 5d Comfort + Navi APL	Maintenance mileage	-
Registration date	13/09/2018	Year	2018	Exterior Color	Black Solid
Odometer	-	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	10/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 155/70/13 Summer 3.0 mm	Hankook 155/70/13 Summer 3.0 mm
Hankook 155/70/13 Summer 4.5 mm	Hankook 155/70/13 Summer 4.5 mm



Exterior

1





Part	Wing
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

2





Part	Door
Position	Front left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4





Part	Wing
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

7





Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

8





Part	Bumper
Position	Front
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

9





Part	Bonnet
Position	-
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

3		<table> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning	5		<table> <tr><td>Part</td><td>Interior tailgate lining</td></tr> <tr><td>Position</td><td>Up</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Interior tailgate lining	Position	Up	Damages	Scratched	Severity	-	Repair mode	Replace
Part	Interior cleaning																								
Position	Front																								
Damages	Stained/dirty																								
Severity	-																								
Repair mode	Cleaning																								
Part	Interior tailgate lining																								
Position	Up																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								
6		<table> <tr><td>Part</td><td>Boot carpet</td></tr> <tr><td>Position</td><td>Down</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Boot carpet	Position	Down	Damages	Scratched	Severity	-	Repair mode	Replace													
Part	Boot carpet																								
Position	Down																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								