

Vehicle details

VIN	NLHA851AA LZ575082	Brand	HYUNDAI	Maintenance date	-
Licence Plate	H0-94-FD	Model	I10 1.0i Blue ActieAuto 5d Comfort APL	Maintenance mileage	-
Registration date	23/01/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	34 856 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	20/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Front Left: Continental 175/65/14 Summer 3.7 mm

Front Right: Continental 175/65/14 Summer 3.6 mm

Rear Left: Continental 175/65/14 Summer 5.1 mm

Rear Right: Continental 175/65/14 Summer 5.1 mm

Exterior

1		Part	Door	2		Part	Roof
		Position	Back left			Position	Centre
		Damages	Dent & Chips			Damages	Dent & Chips
		Severity	Diameter (mm) > 20			Severity	Diameter (mm) > 20
		Repair mode	Repair			Repair mode	Repair

3		Part	Bumper	4		Part	Bumper
		Position	Front			Position	Back left
		Damages	Dented			Damages	Scratched
		Severity	-			Severity	Length (cm) > 10
		Repair mode	Replace			Repair mode	Repair