

Vehicle details

VIN	NLHB351AA LZ640682	Brand	HYUNDAI	Maintenance date	-
Licence Plate	H0-07-SF	Model	i20 1.0 T-GDI 100 ActieAuto 5d Comfort APL	Maintenance mileage	-
Registration date	11/05/2020	Year	2020	Exterior Color	Red Solid
Odometer	90 511 km	Engine size	998	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	13/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓


Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Pirelli 185/65/15 Winter 4.0 mm



Pirelli 185/65/15 Winter 4.0 mm



Pirelli 185/65/15 Winter 7.0 mm

Pirelli 185/65/15 Winter 6.0 mm

Exterior

1



Part	Bonnet
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

3		PartWing PositionBack right DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	4		PartDoor PositionBack left DamagesScratched SeverityLength (cm) > 10 Repair modeRepair
5		PartDoor PositionFront left DamagesDented SeverityDiameter (mm) > 20 Repair modeSmart Repair	6		PartRoof Position- DamagesScratched SeverityLength (cm) > 10 Repair modeRepair