



HYUNDAI i20
i20 1.0 T-GDi 100 Hybrid 48V Creative

VIN NO NLHBN51GXRZ461595
Registration Number GW364WC



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	- km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2024-05-07	France

Inspection Report Summary

Customer	BCAuto Encheres	Report Number	P20250506093051
Inspection Date / Place	2025-05-06 / BCA GARONS	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Not Movable	VAT Type	Qualified - Normal Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour		Engine Size (cc)	998
Engine Size	1.0	No of Doors	5
Body Type	Hatchback	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Rental Car	Imported	
Manufacturer Warrenty			





Equipment


Central locking	Radio	Remote adjusting wing mirrors	Electrically folding wing mirrors
Alloys wheels	Remote central locking		

Equipment Details

Air Conditioning	Yes
------------------	-----

Cosmetic Damage


Component	Damage	Comments
1 Bumper / Back	Paint / Scratch / Line	
2 Bumper / Back	Paint / Chipping	
3 Door / Front Left	Paint / Scratch / Line	
4 Bumper / Front	Bodywork / Breakage / Crack	
5 Front Light / Front Right	Glass Break	
6 Fender / Front Right	Bodywork / Dent / Deformation	
7 Windshield / Front	Glass Break / Impact	
8 Hood	Paint / Chipping	




1. Bumper / Back
Paint / Scratch / Line -



2. Bumper / Back
Paint / Chipping -



3. Door / Front Left
Paint / Scratch / Line -




4. Bumper / Front
Bodywork / Breakage / Crack -




5. Front Light / Front Right
Glass Break -



6. Fender / Front Right
Bodywork / Dent / Deformation -



7. Windshield / Front
Glass Break / Impact -



8. Hood
Paint / Chipping -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut ✔

✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage

❗ Damages or malfunction detected that requires repairs by the buyer

NA Not applicable

⚪ Not tested

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.