

Vehicle details

VIN	NLHBR51GA NZ079241	Brand	HYUNDAI	Maintenance date	-
Licence Plate	L8-47-ZJ	Model	i20 1.0 T-GDI 100 MHEV Premium 5d APL	Maintenance mileage	-
Registration date	22/09/2021	Year	2021	Exterior Color	Black Metallic
Odometer	60 628 km	Engine size	998	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	04/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 195/55/16 Summer 3.0 mm		Michelin 195/55/16 Summer 3.5 mm	
Michelin 195/55/16 Summer 5.5 mm		Michelin 195/55/16 Summer 5.0 mm	

Exterior

1



● ●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

2



●

Part	Wing
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair


3



● ● ●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair


4



● ●

Part	Wing
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Repair

5



● ● ● ● ● ● ●

Part	Door
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



● ● ● ● ●

Part	Door
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	Repair