


Vehicle details

VIN	NMTK33BX8 0R141437	Brand	TOYOTA	Maintenance date	-
Licence Plate	N0-54-DR	Model	C-HR 1.8 Hybrid GR-Sport automaat 5d	Maintenance mileage	-
Registration date	29/09/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	136 481 km	Engine size	1798	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	07/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Electric seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 225/45/19 Summer 1.5 mm		Continental 225/45/19 Summer 1.5 mm	
Continental 225/45/19 Summer 5.5 mm		Continental 225/45/19 Summer 4.5 mm	

Exterior

1		Part	Alloy wheel 19"	2		Part	Door
		Position	Front left			Position	Front left
3		Damages	Scratched	5		Damages	Dent & Chips
		Severity	-			Severity	-
7		Repair mode	Lumpsum repair	8		Repair mode	Repair
9		Part	Unpainted bumper	10		Part	Wing moulding
		Position	Back			Position	Back right
11		Damages	Missing	12		Damages	Scratched
		Severity	-			Severity	-
13		Repair mode	Replace	14		Repair mode	Repair
		Part	Sill cover			Part	Alloy wheel 19"
		Position	Back right			Position	Front right
		Damages	Broken			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Lumpsum repair
		Part	Spoiler			Part	Bumper
		Position	Front			Position	Front
		Damages	Broken			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Repair

15



Part

Roof

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

Interior damage

4



Part

Fabric seat

Position

Front

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning

6



Part

Fabric seat

Position

Back

Damages

Stained/dirty

Severity

-

Repair mode

Cleaning