



Brand:	Jaguar	Mileage(km):	85552
Model:	E-Pace	Number of doors:	5
Model type:	2.0 P200 AWD Premium Edition	Vehicle length (cm):	
License plate:	H225HL	Vehicle width (cm):	
Report code:	9933	Vehicle height (cm):	
Chassis number:	SADFA2BX7K1Z49933	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	05/02/2020	Power(kw):	147
First NL req.:	05/02/2020	Transmission:	Automatic
Color:	Black ☒ Metallic	Number of gears:	9
Weight (kg)(kg):	1887	Displacement(cc):	1997
Empty weight(kg):	1787	Number of cylinders:	4
Wheelbase (cm)(cm):	268	Fuel type:	Petrol
Top speed (km/h):	216	Fuel tank capacity:	
Cons. in the city (l/100 km):	10.1	EU category:	Euro 6
Cons. outside the city (l/100 km):	6.8	Energy label:	G
Average consumption (l/100 km):	8	NL Tax Rate %:	
Acceleration (s):	8.2	CO2 (g/km):	182
Cargo space (l):	1887	Nb. of Axles:	2
Perm. max weight (kg):	2400	APK date:	05/02/2026

opties

☒ Alloy wheels	☒ Exterior mirrors with step light	☒ Climate control (digital)
☒ Leather upholstery	☒ Rain sensor	☒ Climate control (L/R separated)
☒ Daytime running lights	☒ Rear wiper	☒ Large screen navigation
☒ Licht Sensor	☒ Rear view camera	☒ Keyless entry
☒ Towing hook	☒ Rear parking sensors	☒ Keyless entry/start/stop
☒ bots waarschuwing systeem	☒ Front parking sensors	☒ Keyless start/stop
☒ Anti-lock braking system	☒ Towbar with retractable ball	☒ Electrically operated rear windows
☒ ABS	☒ Rear-seat folding (equal parts)	☒ Electrically operated front windows
☒ Airbag(s)	☒ Rear-seat folding (unequal parts)	☒ Electrically folding mirrors
☒ Audio	☒ Luggage cover	☒ Electrically adjustable mirrors
☒ Central locking system	☒ Trunk opens electrically	☒ Electrically adjustable driver's seat
☒ Start/stop system	☒ USB connection	☒ Electrically adjustable passenger seat
☒ Power steering	☒ Bluetooth streaming	☒ Electrically heated driver's seat
☒ Front seats adjustable in height	☒ Bluetooth car kit	☒ Electrically heated passenger seat
☒ Multifunctional steering wheel	☒ Radio	☒ Central armrest front
☒ Remote central locking	☒ WiFi	☒ Adjustable lumbar support driver's seat
☒ Sports package (exterior)	☒ Cruise control	☒ Adjustable lumbar support passenger seat
☒ Metallic finish	☒ Black top interior	☒ Audio control on the steering wheel
☒ Panoramic roof (fixed)	☒ Airconditioning	☒ Leather steering wheel
☒ LED headlights	☒ Airconditioning in the back	☒ Lane assistance
☒ LED rear lights	☒ Climate control	
☒ Exterior mirrors in car body color	☒ Climate control (analog)	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/60 R18	Goodyear	6
Tire left rear	Summer	Alloy	235/60 R18	Goodyear	6
Tire right front	Summer	Alloy	235/60 R18	Goodyear	6
Tire right rear	Summer	Alloy	235/60 R18	Goodyear	6

Additional information

No. of keys:	2	☐ Luxury key	☐ Instruction booklet	☒ Airco works
Interior color:	Black	Maintenance booklet:		☒ Odorless
Upholstery:	Leder			☒ Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		☒ Display ok
No. of headrests:	5	Last turn mileage(km):		☒ Vehicle special usage (None)

⚠ Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Cleaning)

🔧 Damages

⊛ Not acceptable



Front bumper - Break



Front bumper - Break



Rear bumper - Scratch



Rear bumper - Scratch



Rear right door - Scratch



Front left door - Paint repair



Right outside mirror - Break










Bestuurderstoel beschadigd

🔧 Damages

⊛ Acceptable

⚙ Extra options







AUTOF[▲]CTOR
SOFTWARE FOR AUTOMOTIVE