

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	249926
License plate	2AJP425
Vehicle identification number	SADHA2B14M1613888
Dossier	2020 321 110
Make	Jaguar I-Pace S
Mileage	33128.00
First registration	16/04/2021
	20/11/2024

CHECK POINTS

Description	Number	Present	Remark
Certificate of conformity		Y	
Registration certificate		Y	
Charging cable	2	Y	
Original license plate		Y	
Repair kit		Y	
Spare wheel			
Keys	2	Y	
Towbar (+keys)			
RunOnFlat			





DAMAGES

Damages	Type	Acceptable
201	Rocker Panel Right // Smart Repair Medium	N
192	Door Rear Right // Smart Repair Large	Y
236	Wing Front right // Polish	Y
240	Headlight / Front Right/ Repair	Y
16	Bumper Front // Polish	Y
222	Side View Mirror Right // Painting	N
645	Rear Right Door Interior Coating / Reflector / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
133	Bumper Rear // Painting	N
116	Wing Rear Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	N
83	Door Front Left // Painting	N
72	Side View Mirror Left // Painting	Y

Damage Pictures




Seat Front Left / Bottom Coating / Replace



Bumper Front // Painting



Bumper Rear // Polish



Rocker Panel Left / Cover Not Painted / Replace