


**JAGUAR I-PACE: 1YTF269**

Vinnnumber:	<b>SADHA2B18M1606569</b>	Versionname:	<b>SE</b>
First Registrationdate:	<b>7/12/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>109194</b>	Power Kw:	<b>294</b>
Bodytype:		Body colour:	<b>Red</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1114</b>
Fueltype:	<b>Electric</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		
Registration Certificate Home (BE):	<b>No</b>		

**Options**

Number of keys total:	<b>2</b>	Panoramic roof	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**
**Tyres**

	<b>235/65/18/110 H</b>			
Winter tyres:	Fr.L.	<b>Vredestein: 3 mm</b>	Fr.R.	<b>Vredestein: 4 mm</b>
	Re.L.	<b>Vredestein: 3 mm</b>	Re.R.	<b>Vredestein: 4 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>4.0</b>
Tyre profile depth RL				<b>3.0</b>
Tyre profile depth RR				<b>4.0</b>
Tyre size FL				<b>235/65 R 18 110 H</b>
Tyre size FR				<b>235/65 R 18 110 H</b>
Tyre size RL				<b>235/65 R 18 110 H</b>
Tyre size RR				<b>235/65 R 18 110 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>2480</b>
Tyre make FR				<b>2480</b>
Tyre make RL				<b>2480</b>
Tyre make RR				<b>2480</b>

**Assistance equipment**

Number of charging cables (normal)	<b>1</b>
Number of charging cables (rapid charge)	<b>1</b>

<b>Total cost ex VAT</b>	<b>1147,58</b>
<b>Interior, Worn, Acceptable</b>	<b>0,00</b>



Bumper moulding F, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Wheel arch cover FL, Deformed / Strained, Acceptable 0,00



Door FL, Dent(s) and scratch(es), Repair and paint (complete) 534,95




A-pillar left, Scratch(es), Acceptable 0,00



Alloy rim RL polished, Scratch(es), Repair and paint (complete) 204,21



Alloy rim RR polished, Scratch(es), Acceptable 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



