



<b>Brand:</b>	Jaguar	<b>Mileage(km):</b>	179331
<b>Model:</b>	I-Pace	<b>Number of doors:</b>	5
<b>Model type:</b>	EV320 S Business Pack 90 kWh	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	K856BJ	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	9750	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	SADHA2B1XM1609750	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front+Rear
<b>First int. reg.:</b>	20/11/2020	<b>Power(kw):</b>	235
<b>First NL req.:</b>	20/11/2020	<b>Transmission</b>	Automatic
<b>Color:</b>	Grey <input checked="" type="checkbox"/> Metallic	<b>Number of gears</b>	
<b>Weight (kg)(kg):</b>	2244	<b>Displacement(cc):</b>	
<b>Empty weight(kg):</b>	2144	<b>Number of cylinders:</b>	
<b>Wheelbase (cm)(cm):</b>	299	<b>Fuel type:</b>	Electric
<b>Top speed (km/h):</b>	200	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>		<b>EU category:</b>	
<b>Cons. outside the city (l/100 km):</b>		<b>Energy label:</b>	A
<b>Average consumption (l/100 km):</b>		<b>NL Tax Rate %:</b>	8
<b>Acceleration (s):</b>	6.4	<b>CO2 (g/km):</b>	1
<b>Cargo space (l):</b>	2244	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	2670	<b>APK date:</b>	20/11/2026

## opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Exterior mirrors with step light	<input checked="" type="checkbox"/> Climate control
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Climate control (analog)
<input checked="" type="checkbox"/> Air suspension	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Climate control (digital)
<input checked="" type="checkbox"/> Digital dashboard	<input checked="" type="checkbox"/> 360 ° camera system	<input checked="" type="checkbox"/> Climate control (L/R separated)
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Keyless entry
<input checked="" type="checkbox"/> bots waarschuwing systeem	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Keyless entry/start/stop
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Rear-seat folding (equal parts)	<input checked="" type="checkbox"/> Keyless start/stop
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Rear-seat folding (unequal parts)	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Charging cable 380V	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Start/stop system	<input checked="" type="checkbox"/> Charging cable 220V	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Bluetooth streaming	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> DAB+	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Leather sports steering wheel
<input checked="" type="checkbox"/> Sports package (exterior)	<input checked="" type="checkbox"/> Radio	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> WiFi	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> LED headlights	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Pedestrian safety system
<input checked="" type="checkbox"/> Headlight washers	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Dead angle assistance
<input checked="" type="checkbox"/> LED rear lights	<input checked="" type="checkbox"/> Airconditioning	
<input checked="" type="checkbox"/> Exterior mirrors in car body color	<input checked="" type="checkbox"/> Airconditioning in the back	

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	245/50 R20	Goodyear	4
Tire left rear	Summer	Alloy	245/50 R20	Goodyear	3
Tire right front	Summer	Alloy	245/50 R20	Goodyear	4
Tire right rear	Summer	Alloy	245/50 R20	Goodyear	3

## Additional information

<b>No. of keys:</b>	1	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	24/01/2023	<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

161432

☒ Vehicle special usage (None)

## Cleaning

☒ Clean inside (Interior is clean)

☒ Clean outside (Cleaning)

## Damages

 Not acceptable



Front left rim - Scratch



Front bumper - Scratch



Rear bumper - Scratch



Front left door - Restyle dent



Front left door - Scratch



Windscreen - Pip

## Damages

 Acceptable

## Extra options







