

Check-in rapport

SAJAB4BN7HCP04917

Title	Jaguar XE 20d Automatik "Prestige"	VIN	SAJAB4BN7HCP04917
Category	Saloon, 4 door	Transmission	Automatic
Engine type	Diesel	Colour	black
Fuel type	Diesel	Colour name	santoriniblack
Emission class	EURO 6	Mileage	146700
Capacity	2000	Total number of owners	
Power output KW	132	Number of keys	2
Power output PS	180	Tax	Tax on difference
First registration	2017-03-01		

Options			
• ABS	• Keyless-Go	• Particle filter	• Stability program DSC (Dynamic Stability Control)
• Airbags: 6	• Lane keeping system	• Power steering	• Start/stop system
• Automatic dimming internal mirror	• Leather steering wheel	• Radio	• Telephone: Preparation with Bluetooth
• Automatic tailgate	• Multi-function steering wheel	• Rain sensor	• Tinted rear windows
• Climatronic	• On-board computer	• Remote central locking	• Tyre Pressure Indicator TPI
• Cruise control	• Paddle shift steering wheel	• Reverse camera	
• Electric windows front and rear	• Panorama sunroof	• Satnav with map views: InControl Touch	
• Heated windscreen	• Parking aid PDC (Park Distance Control) front/rear	• Side mirror electrically adjustable	

Extra options

Comfort package (electric tailgate operation, keyless start)	
Navigation system InControl Touch including voice control (JaguarVoice)	
Panoramic roof (glass)	
Parking package (parking aid) extended (driver assistance system: parking assistance system (Park Assist), Park Distance Control (PDC) front and rear)	
Rear side windows tinted	
Heated windscreen	
Blind spot assistant	
USB port	
AUX-IN port	
Comfort package (electric tailgate operation, keyless start)	
Navigation system InControl Touch including voice control (JaguarVoice)	
Panoramic roof (glass)	
Parking package (parking aid) extended (driver assistance system: parking assistance system (Park Assist), Park Distance Control (PDC) front and rear)	
Rear side windows tinted	
Heated windscreen	
Blind spot assistant	
USB port	
AUX-IN port	

Seats

- Number of seats 5
- Leather: black
- Centre armrest: front and rear
- Split rear seat

Seats Count

5

Doors

4

Accident / Prior damage

Repaired previous damages:

Damage amount: Amount unknown

Images





View of instrument panel



Key



Body Damage



Left side mirror  
Scratch



Left front door  
Scratch



Left back side section  
Scratch



Tailgate  
Scratch



Rear bumper middle  
Scratch



Right back side section  
Scratch



Right back side section  
Scratch



Right rear door  
Scratch



Right front door  
Scratch



Front right bumper  
Scratch



Left front rim  
Scratch




Left back rim  
Scratch



Right back rim  
Scratch



Right front rim  
Scratch



Scratch  
Traces of impact on door  
edge front left

Scratch  
Traces of impact on door  
edge back right

Scratch  
Traces of impact on door  
edge front right

Major stone chip damage  
Front section general

Interior Damage





Driver's seat  
Wear



Passenger's seat  
Wear



Rear seat  
Wear



Carpeted floor  
Wear, Stains



Steering wheel  
Wear



Door side cladding rear left  
Damaged



Door side cladding rear right  
Damaged



Door side cladding front  
right  
Wear, Stains



Boot  
Wear, Stains