



Land Rover Discovery Sport (KKL): 1XCR447

Vinnnummer:	SALCA2BN3LH849875	Versionname:	Discovery Sport SE D150 2.0d 150pk/cv 5p AWD Aut.
First Registrationdate:	19/11/2019	Fiscalpower:	
Expertise Mileage:	106442	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

235/50/20/104 W				
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/50 R 20 104 W
Tyre size FR				235/50 R 20 104 W
Tyre size RL				235/50 R 20 104 W
Tyre size RR				235/50 R 20 104 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door panel RL, Tear, Smart repair



Bonnet, Chemical polution, Repair and paint (complete)



Bumper F, Scratch(es), Spot repair



Alloy rim FL polished, Chemical polution, Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim RL, Scratch(es), Replace



Alloy rim RL polished, Chemical polution, Repair and paint (complete)



Tyre RL, Tear, Replace



Tailgate / Boot, Scratch(es), Acceptable



Alloy rim RR polished, Chemical polution, Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Alloy rim FR polished, Chemical polution, Repair and paint (complete)

