



Land Rover Discovery Sport: K697BN

Vinnumber:	SALCA2BT9LH879171	Versionname:	Discovery Sport 1.5 P300e PHEV 227kW 4WD S automaat (NEDC)
First Registrationdate:	21/11/2020	Fiscalpower:	
Expertise Mileage:	154093	Power Kw:	146
Bodytype:		Body colour:	Silicon Silver premium metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	731
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment	
Number keys remote	2	Lining leather	
GPS		Central consol F	
Autom climate control		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Radio multimedia		Front parking sensors	
		Rear parking sensors	

Degree of wear

	235/60/18/107 H			
Winter tyres:	Fr.L.	Bridgestone: 2,8 mm	Fr.R.	Bridgestone: 3,2 mm
	Re.L.	Bridgestone: 3,3 mm	Re.R.	Bridgestone: 3 mm
Tyre profile depth FL				2.8
Tyre profile depth FR				3.2
Tyre profile depth RL				3.3
Tyre profile depth RR				3.0
Tyre size FL				235/60 R 18 107 H
Tyre size FR				235/60 R 18 107 H
Tyre size RL				235/60 R 18 107 H
Tyre size RR				235/60 R 18 107 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Door FL: Scratch(es), Repair and paint (complete)



Bonnet: Chemical polution, Polish



Windscreen, Stone chip(s), Windscreen repair



Outside rear-view mirror housing R, Scratch(es), Polish



Charging cable (normal), Missing, Replace



Roof, Chemical polution, Polish

