



Land Rover Discovery: 2BRC789

Vinnumber:	SALCB2DN0NH912301	Versionname:	
First Registrationdate:	22/02/2022	Fiscalpower:	
Expertise Mileage:	91181	Power Kw:	120
Bodytype:		Body colour	Red
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2730
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	Headlighting LED	Front parking sensors	
Type of GPS	GPS big screen color	Rear parking sensors	
Type of Lining	Lining artificial leather	Type of Tow bar	Tow bar removable
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	235/60/18/107 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				235/60 R 18 107 V
Tyre size FR				235/60 R 18 107 V
Tyre size RL				235/60 R 18 107 V
Tyre size RR				235/60 R 18 107 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	0,00
Door panel FL, Worn, Acceptable	0,00



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------



Wing trim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Outside rear-view mirror housing L, Scratch(es), Acceptable	0,00
---	------



Wing RL, Scratch(es), Acceptable	0,00
----------------------------------	------



Tailgate / Boot, Scratch(es), Acceptable	0,00
--	------



Rear light R tailgate, Waterinfiltration, Acceptable	0,00
--	------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------

