



LAND ROVER Range Rover Velar 2017  
Diesel  
Range Rover Velar 2.0 i4 R-Dynamic S  
240cv auto

VIN NO SALYA2BN8JA719327  
Registration Number FP661XX



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-07-22	-	-	81947 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2018-04-24	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250915102919
Inspection Date / Place	2025-09-15 / BCA Lodi	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualified
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Silver	Engine Size (cc)	1999
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Leather
Charging Cables		NEDC CO2 Rating (q/km)	154

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			









Equipment

Central locking	Rain sensitive windscreen wipers	Alloys wheels	Electrically adjustable seats
Front parking sensors	Sunroof	Parcel Shef	Remote central locking
Tow ball	Trip Computer	Stability control	Power assisted steering
Rear parking sensors	Digital Radio	Electrically folding wing mirrors	Satellite navigation
Volante multifuncion	Remote adjusting wing mirrors	Cruise control	Traction control

Tyre Mobility Kit

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	MICHELIN MICHELIN-LATITUDE TOUR HP	255/50//R20 - 109W / 4 mm
	MICHELIN MICHELIN-LATITUDE TOUR HP	255/50//R20 - 109W / 4 mm
	MICHELIN MICHELIN-LATITUDE TOUR HP	255/50//R20 - 109W / 4 mm
	MICHELIN MICHELIN-LATITUDE TOUR HP	255/50//R20 - 109W / 4 mm




Cosmetic Damage

21 Danni




2 Danni



Component		Damage	Comments
1	TV DVD Screen / Front	Interior / Scratched	
2	Seat / Front Left	Interior / Broken	
3	Windshield / Front	Glass Break / Impact	
4	Hood	Paint / Scratch / Line	
5	Bumper / Front	Bodywork / Dent	
6	Rim / Front Left	Out of Bodywork / Scratch	
7	Mirror Shell / Front Left	Paint / Scratch / Line	
8	Door / Front Left	Paint / Scratch / Line	
9	Door / Back Left	Paint / Scratch / Line	
10	Fender / Back Left	Bodywork / Dent	
11	Rim / Back Left	Out of Bodywork / Scratch	
12	Bumper / Back	Bodywork / Dent	

13	Tailgate	Bodywork / Dent
14	Fender / Back Right	Paint / Scratch / Line
15	Rim / Back Right	Out of Bodywork / Scratch
16	Door / Back Right	Bodywork / Dent
17	Door / Front Right	Paint / Scratch / Line
18	Mirror Shell / Front Right	Paint / Scratch / Line
19	Fender / Front Right	Paint / Chipping
20	Rim / Front Right	Out of Bodywork / Scratch
21	Pillar / Front Right	Bodywork / Dent
22	Roof	Bodywork / Dent
23	Sunroof	Glass Break / Impact




1. TV DVD Screen / Front Interior / Scratched -



2. Seat / Front Left Interior / Broken -



3. Windshield / Front Glass Break / Impact -



4. Hood Paint / Scratch / Line -



5. Bumper / Front Bodywork / Dent -



6. Rim / Front Left Out of Bodywork / Scratch -





7. Mirror Shell / Front Left  
Paint / Scratch / Line -



8. Door / Front Left  
Paint / Scratch / Line -



9. Door / Back Left  
Paint / Scratch / Line -



10. Fender / Back Left  
Bodywork / Dent -



11. Rim / Back Left  
Out of Bodywork / Scratch -



12. Bumper / Back  
Bodywork / Dent -





13. Tailgate  
Bodywork / Dent -



14. Fender / Back Right  
Paint / Scratch / Line -




15. Rim / Back Right  
Out of Bodywork / Scratch -



16. Door / Back Right  
Bodywork / Dent -




17. Door / Front Right  
Paint / Scratch / Line -



18. Mirror Shell / Front Right  
Paint / Scratch / Line -




19. Fender / Front Right  
Paint / Chipping -




20. Rim / Front Right  
Out of Bodywork / Scratch -



21. Pillar / Front Right  
Bodywork / Dent -



22. Roof  
Bodywork / Dent -



23. Sunroof  
Glass Break / Impact -



## Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

## Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	✓		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓		
Equipments Test			
Steering   Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	✓
Engine Noise	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			