



LAND ROVER RANGE ROVER VELAR: GF-518-PA

Vinnnumber:	SALYA2BY5NA336400	Versionname:	
First Registrationdate:	31/03/2022	Fiscalpower:	
Expertise Mileage:	51805	Power Kw:	
Bodytype:	SUV	Body colour:	Grey
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4x4	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total:	2	Sun Roof electric
Number keys remote:	2	Rear view camera
GPS big screen color		
GPS storage		
GPS storage	HD	

Degree of wear

255/50/20/109 W				
Summer tyres:	Fr.L.	Goodyear: 80%	Fr.R.	Goodyear: 70%
	Re.L.	Goodyear: 75%	Re.R.	Goodyear: 75%
Tyre profile depth FL				3.1
Tyre profile depth FR				3.6
Tyre profile depth RL				3.5
Tyre profile depth RR				3.5
Tyre size FL				255/50 R 20 109 W
Tyre size FR				255/50 R 20 109 W
Tyre size RL				255/50 R 20 109 W
Tyre size RR				255/50 R 20 109 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	1		

Door seal FL, Tear, Replace



Tyres, No damage, Acceptable



Tyre FL, Out of tolerance, Replace



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Door RR, Scratch(es), Paint



Luggage compartment cover, Missing, Replace



Internal boot lining L, Scratch(es), Repair/replace (lump sum)



Rear roof pillar covering L, Scratch(es), Repair/replace (lump sum)



Rear bulkhead lining, Scratch(es), Repair/replace (lump sum)



Rear roof pillar covering R, Scratch(es), Repair/replace (lump sum)



Internal boot lining R, Scratch(es), Repair/replace (lump sum)



Tailgate / Boot, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Repair/replace (lump sum)

