



Land Rover Range Rover Velar: P086JR

Vinnumber:	SALYA2BY6NA336213	Versionname:	Range Rover Velar 2.0 P400E PHEV 297kW 4WD R-Dyn HSE Aut
First Registrationdate:	30/03/2022	Fiscalpower:	
Expertise Mileage:	151549	Power Kw:	221
Bodytype:		Body colour:	Eiger Grey - metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	240
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Sun Roof electric
Windows electric F		Panoramic roof
Radio multimedia		Central consol F
		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	265 / 45 / 21 / 104 / W / Aluminium	5,8 mm	Michelin	Summer
	Right	265 / 45 / 21 / 104 / W / Aluminium	5,5 mm	Michelin	Summer
Rear	Left	265 / 45 / 21 / 104 / W / Aluminium	5,2 mm	Michelin	Summer
	Right	265 / 45 / 21 / 104 / W / Aluminium	5,2 mm	Michelin	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)





Roof pillar L, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Spoiler FR, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Door FR, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)

