



LAND ROVER RANGE ROVER VELAR: GH-130-MG

Vinnnummer:	SALYA2BY9NA342376	Versionname:	
First Registrationdate:	12/07/2022	Fiscalpower:	
Expertise Mileage:	29869	Power Kw:	
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total:	1	Sun Roof electric
Number keys remote:	1	Luggage cover
GPS big screen color:		Rear view camera

Degree of wear

	255/50/20/109 W			
Summer tyres:	Fr.L.	Goodyear: 40%	Fr.R.	Goodyear: 45%
	Re.L.	Goodyear: 35%	Re.R.	Goodyear: 35%
Tyre profile depth FL				5.5
Tyre profile depth FR				5.2
Tyre profile depth RL				5.8
Tyre profile depth RR				6.0
Tyre size FL				255/50 R 20 109 W
Tyre size FR				255/50 R 20 109 W
Tyre size RL				255/50 R 20 109 W
Tyre size RR				255/50 R 20 109 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		

Remote ignition key (no insert), Missing, Forfeit



Tyres, No damage, Acceptable



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Alloy rim RL, Scratch(es), Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror housing L, Scratch(es), Paint



Bumper moulding FR, Deformed / Strained, Replace and paint



Bumper grille, Broken, Replace



Bumper spoiler F, Unclassped, Dismount/Mount



Bumper F, Scratch(es), Paint

