



LAND ROVER RANGE ROVER EVOQUE: 1YUF982				
Vinnumber:	SALZA2BNXLH097215	Versionname:	D150 AWD Auto S	
First Registrationdate:	30/03/2020	Fiscalpower:		
Expertise Mileage:	101653	Power Kw:	110	
Bodytype:		Body colour	Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3411	
Fueltype:	Hybrid Diesel			
Maintenance	OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Seats electric F L		
Cruise Control		Seats electric F R		
Steering wheel multifunctional		Panoramic roof		
Radio multimedia		Luggage cover		
Type of headlighting	Headlighting LED	Front parking sensors		
Type of GPS	GPS big screen color	Rear parking sensors		
Type of Lining	Lining leather	Type of Tow bar	No Tow bar	
Type of climate control	Autom climate control			
Adaptive cruise control				
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
235/65/17/108 W				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				235/65 R 17 108 W
Tyre size FR				235/65 R 17 108 W
Tyre size RL				235/65 R 17 108 V
Tyre size RR				235/65 R 17 108 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				259
Tyre make RR				259
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			3624,91	
Door FL, Dent(s) and scratch(es), Acceptable			0,00	



Door RL, Chemical polution, Repair and paint (complete) 521,40



Wing RL, Chemical polution, Repair and paint (complete) 504,77



Supplementary brake light, Scratch(es), Replace 191,04



Brand badge R, Worn, Replace 51,74



Tailgate / Boot, Scratch(es), Repair and paint (complete) 494,10



Bumper moulding R, Deformed / Strained, Replace 314,29



Bumper R, Scratch(es), Acceptable 0,00



Wheel aperture RR, Scratch(es), Acceptable	0,00
--	------



Wing RR, Chemical polution, Repair and paint (complete)	504,77
---	--------



Door RR, Chemical polution, Repair and paint (complete)	521,40
---	--------



Outside rear-view mirror housing R, Scratch(es), Acceptable	0,00
---	------



Door FR, Scratch(es), Repair and paint (complete)	521,40
---	--------

