


Vehicle details

VIN	SB1K93BE6 0E222395	Brand	TOYOTA	Maintenance date	-
Licence Plate	L8-59-GZ	Model	Corolla Hatchback 1.8 Hybrid Comfort 5d APL	Maintenance mileage	-
Registration date	01/06/2021	Year	2021	Exterior Color	White Solid
Odometer	44 693 km	Engine size	1798	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	22/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 195/65/15 Summer 7.5 mm		Pirelli 195/65/15 Summer 7.0 mm	
Bridgestone 195/65/15 Summer 6.0 mm		Bridgestone 195/65/15 Summer 5.5 mm	

Exterior

1		Part	Wing	2		Part	Bumper
		Position	Front right			Position	Front
		Damages	Chemical deposit			Damages	Dent & Chips
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	Lumpsum repair			Repair mode	Repair



DEKRA Automotive Solutions



3

Part	Roof
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair