


Vehicle details

VIN	SB1KA3BE0 0E027674	Brand	TOYOTA	Maintenance date	-
Licence Plate	P3-27-SR	Model	Corolla Hatchback 1.2 Turbo Active 5d	Maintenance mileage	-
Registration date	24/08/2022	Year	2022	Exterior Color	Black Metallic
Odometer	70 659 km	Engine size	1197	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	06/02/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Pirelli 205/55/16 All seasons 5.0 mm



Pirelli 205/55/16 All seasons 5.0 mm



Pirelli 205/55/16 All seasons 7.0 mm

Pirelli 205/55/16 All seasons 7.0 mm

Exterior

1



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

●●●●

2



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	Number > 2
Repair mode	Repair

●●●●●

3



Part	Door
Position	Back right
Damages	Dented
Severity	Number > 2
Repair mode	Smart Repair

●●●

4



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●

5



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●


6



Part	Alloy wheel 16"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

●●

7



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

●●

8



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

●●