


Vehicle details

VIN	SB1Z53BE1 0E058449	Brand	TOYOTA	Maintenance date	-
Licence Plate	J6-75-SR	Model	Corolla Touring Spor 2.0 Hybrid GR-Sport PLUS 5d	Maintenance mileage	-
Registration date	29/10/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	159 360 km	Engine size	1987	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	21/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 225/40/18 Summer 4.0 mm		Pirelli 225/40/18 Summer 4.0 mm	
Falken 225/40/18 Summer 4.0 mm		Falken 225/40/18 Summer 3.0 mm	

Exterior

1		Part Alloy wheel 18" Position Front left Damages Scratched Severity - Repair mode Lumpsum repair	4		Part Wing Position Back left Damages Scratched Severity Length (cm) > 10 Repair mode Repair
6		Part Alloy wheel 18" Position Back right Damages Scratched Severity - Repair mode Lumpsum repair	7		Part Alloy wheel 18" Position Front right Damages Scratched Severity - Repair mode Lumpsum repair
8		Part Bumper Position Front Damages Scratched Severity Length (cm) > 10 Repair mode Repair			

Interior damage

2		Part Interior cleaning Position Front Damages Stained/dirty Severity - Repair mode Cleaning			
3		Part Interior cleaning Position Back Damages Stained/dirty Severity - Repair mode Cleaning	5		Part Interior tailgate lining Position - Damages Scratched Severity - Repair mode Smart Repair