



Toyota Corolla: R595KP

Vinnumber:	SB1Z93BE90E335613	Versionname:	Corolla 1.8 Hybrid 90kW Comfort Touring Sports CVT
First Registrationdate:	13/10/2022	Fiscalpower:	
Expertise Mileage:	91839	Power Kw:	72
Bodytype:		Body colour	Night Sky Black metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Hybrid Petrol	Parking lot	159
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Tow bar removable

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 65 / 15 / 91 / H / Steel	5,7 mm	Bridgestone	Summer
	Right	195 / 65 / 15 / 91 / H / Steel	4,5 mm	Bridgestone	Summer
Rear	Left	195 / 65 / 15 / 91 / H / Steel	6,4 mm	Bridgestone	Summer
	Right	195 / 65 / 15 / 91 / H / Steel	5,0 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



Door FL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)





Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Wing RR, Scratch(es), Repair and paint (complete)



Roof pillar R, Chemical polution, Polish



Door RR, Chemical polution, Polish



Door FR, Scratch(es), Repair and paint (complete)



Wing FR, Chemical polution, Polish



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Roof, Dent(s) and scratch(es), Repair and paint (complete)

