


Vehicle details

VIN	SB1ZS3JE0 0E409040	Brand	TOYOTA	Maintenance date	-
Licence Plate	SB-31-0X	Model	Auris Touring Sports 1.8 Hybrid Dynamic Automaat 5	Maintenance mileage	-
Registration date	13/03/2018	Year	2018	Exterior Color	Black Metallic
Odometer	299 846 km	Engine size	1798	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	22/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Scratched

Length (cm) > 10

Repair

2



Part

Position

Damages

Severity

Repair mode

Alloy wheel 16"

Front left

Scratched

-

Lumpsum repair

3



Part

Position

Damages

Severity

Repair mode

Door

Front left

Scratched

Length (cm) > 10

Repair

4



Part

Position

Damages

Severity

Repair mode

Alloy wheel 16"

Front right

Scratched

-

Lumpsum repair

5



Part

Position

Damages

Severity

Repair mode

Door

Front right

Dent & Chips

Diameter (mm) > 20

Repair

6



Part

Position

Damages

Severity

Repair mode

Door

Back right

Dented

Diameter (mm) > 20

Smart Repair

7



Part

Position

Damages

Severity

Repair mode

Wing

Back right

Dented

Diameter (mm) > 20

Smart Repair

8



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Blister

-

Replace

Interior damage

9



Part	Fabric seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning