



NISSAN Note
Note 1.4

VIN NO SJNFAAE11U2116835
Registration Number 11U2116835



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-08-01	2	2	109467 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-03-21	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251006121259
Inspection Date / Place	2025-10-06 / BCA Neuss	Cosmetic Grade	5


Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1386
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	139

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Front fog lamps	Remote central locking	Stability control	Leather steering wheel
USB Socket	Alloys wheels	Auxiliary Socket	Cruise control
Remote adjusting wing mirrors	Satellite navigation	CD Player	Radio

Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	16
Extra Wheel / Tyre Set	Winter Tyres - Steel		

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	3	Extra Wheel - 2 Tyre Depth	3
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

30 Schäden



4 Schäden



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Loose	
2	Panel Filling / Back Left	Interior / Loose	
3	Pillar / Back Left	Bodywork / Dent / Dent	
4	Pillar / Back Left	Bodywork / Dent / Dent	
5	Panel Filling / Back Right	Interior / Loose	
6	Panel Filling / Front Right	Interior / Loose	
7	Rocker Panel / Center Right	Bodywork / Dent / Dent	
8	Rocker Panel / Center Right	Bodywork / Dent / Dent	
9	Fender / Back Left	Paint / Poor Previous Repair	
10	Door / Back Right	Paint / Poor Previous Repair	
11	Door / Front Right	Paint / Poor Previous Repair	
12	Front Light / Front Right	Glass Break	

13	Front Light / Front Left	Glass Break
14	Hood	Bodywork / Dent / Dent
15	Hood	Bodywork / Dent / Dent
16	Hood	Bodywork / Dent / Dent
17	Corner Bumper / Front Right	Paint / Scratch / Scuff
18	Corner Bumper / Front Right	Paint / Scratch / Scuff
19	Bumper / Front	Paint / Scratch / Scuff
20	Rim / Front Left	Out of Bodywork / Scratch
21	Bumper / Front	Paint / Scratch / Scuff
22	Fender / Front Left	Paint / Scratch / Scuff
23	Door / Back Left	Bodywork / Dent / Dent
24	Fender / Back Left	Bodywork / Dent / Dent
25	Corner Bumper / Back Left	Paint / Scratch / Scuff
26	Bumper / Back	Paint / Scratch / Scuff
27	Rim / Back Right	Out of Bodywork / Scratch
28	Roof	Bodywork / Dent / Dent
29	Fender / Back Right	Paint / Scratch / Scuff
30	Door / Back Right	Bodywork / Dent / Dent
31	Door / Back Right	Paint / Scratch / Scuff
32	Door / Back Right	Paint / Scratch / Scuff
33	Rim / Front Right	Out of Bodywork / Scratch
34	Door / Back Left	Paint / Scratch / Scuff



1. Panel Filling / Front Left
Interior / Loose -



2. Panel Filling / Back Left
Interior / Loose -



3. Pillar / Back Left
Bodywork / Dent / Dent -



4. Pillar / Back Left
Bodywork / Dent / Dent -



5. Panel Filling / Back Right
Interior / Loose -



6. Panel Filling / Front Right
Interior / Loose -



7. Rocker Panel / Center Right
Bodywork / Dent / Dent -



8. Rocker Panel / Center Right
Bodywork / Dent / Dent -



9. Fender / Back Left
Paint / Poor Previous Repair -



10. Door / Back Right
Paint / Poor Previous Repair -




11. Door / Front Right
Paint / Poor Previous Repair -




12. Front Light / Front Right
Glass Break -




13. Front Light / Front Left
Glass Break -



14. Hood
Bodywork / Dent / Dent -



15. Hood
Bodywork / Dent / Dent -



16. Hood
Bodywork / Dent / Dent -



17. Corner Bumper / Front Right
Paint / Scratch / Scuff -



18. Corner Bumper / Front Right
Paint / Scratch / Scuff -




19. Bumper / Front
Paint / Scratch / Scuff -




20. Rim / Front Left
Out of Bodywork / Scratch -



21. Bumper / Front
Paint / Scratch / Scuff -



22. Fender / Front Left
Paint / Scratch / Scuff -



23. Door / Back Left
Bodywork / Dent / Dent -



24. Fender / Back Left
Bodywork / Dent / Dent -




25. Corner Bumper / Back Left
Paint / Scratch / Scuff -



26. Bumper / Back
Paint / Scratch / Scuff -




27. Rim / Back Right
Out of Bodywork / Scratch -




28. Roof
Bodywork / Dent / Dent -




29. Fender / Back Right
Paint / Scratch / Scuff -



30. Door / Back Right
Bodywork / Dent / Dent -




31. Door / Back Right
Paint / Scratch / Scuff -



32. Door / Back Right
Paint / Scratch / Scuff -



33. Rim / Front Right
Out of Bodywork / Scratch -



34. Door / Back Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

AC / Heating System	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	NA
--------------	---	---------------	----

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)