


Vehicle details

VIN	SJNFAAF16 U1023435	Brand	NISSAN	Maintenance date	-
Licence Plate	H4-91-SB	Model	Juke DIG-T 117 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	02/05/2020	Year	2020	Exterior Color	Brown Metallic
Odometer	122 839 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	08/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Spare key	✗
User manual	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Bridgestone 215/60/17 Summer 3.0 mm		Bridgestone 215/60/17 Summer 3.0 mm	
Bridgestone 215/60/17 Summer 6.0 mm		Bridgestone 215/60/17 Summer 6.0 mm	

Exterior

4		PartStep plate PositionFront left DamagesDent & Chips Severity- Repair modeFor info	5		PartStep plate PositionBack left DamagesDent & Chips Severity- Repair modeFor info
8		PartDoor PositionBack left DamagesScratched SeverityLength (cm) > 10 Repair modeRepair	9		PartTailgate / Boot door Position- DamagesDent & Chips SeverityDiameter (mm) > 20 Repair modeRepair
10		PartAlloy wheel 17" PositionFront left DamagesScratched Severity- Repair modeLumpsum repair	11		PartLower bumper PositionBack DamagesScratched SeverityLength (cm) > 10 Repair modeRepair
14		PartStep plate PositionBack right DamagesDent & Chips Severity- Repair modeFor info	15		PartStep plate PositionFront right DamagesDent & Chips Severity- Repair modeFor info
16		PartAlloy wheel 17" PositionFront right DamagesScratched Severity- Repair modeLumpsum repair			

Interior damage

1		PartSpare key Position- DamagesMissing Severity- Repair modeReplace			
2		PartFabric door lining PositionFront left DamagesScratched Severity- Repair modeSmart Repair	3		PartFabric door lining PositionBack left DamagesScratched Severity- Repair modeSmart Repair

6		Part Fabric seat Position Front Damages Stained/dirty Severity - Repair mode Cleaning	7		Part Fabric seat Position Back Damages Stained/dirty Severity - Repair mode Cleaning
12		Part Interior tailgate lining Position - Damages Scratched Severity - Repair mode Smart Repair	13		Part Interior cleaning Position Back Damages Stained/dirty Severity - Repair mode Cleaning