

Vehicle details

VIN	SJNFAAF16 U1047692	Brand	NISSAN	Maintenance date	-
Licence Plate	J9-22-JX	Model	Juke DIG-T 117 ActieAuto 5d Acenta APL	Maintenance mileage	-
Registration date	21/08/2020	Year	2020	Exterior Color	White Solid
Odometer	53 615 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	10/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Bridgestone 215/60/17 Summer 4.5 mm		Bridgestone 215/60/17 Summer 5.5 mm	
Bridgestone 215/60/17 Summer 5.5 mm		Bridgestone 215/60/17 Summer 5.0 mm	

Exterior

1



●●●

Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

2



●●●●

Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



●●●

Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



●●●●●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

7



●●

Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

8



●●

Part	Exterior door mirror shell
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



●●

Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

10



●●

Part	Exterior door mirror shell
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

3



Part	Interior cleaning
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

5



Part	Wiper blade cover
Position	Back
Damages	Broken
Severity	-
Repair mode	Replace