


Vehicle details

VIN	SJNFAAF16 U1048348	Brand	NISSAN	Maintenance date	-
Licence Plate	J8-95-KL	Model	Juke DIG-T 117 ACTI 5d Acenta APL 5d	Maintenance mileage	-
Registration date	31/08/2020	Year	2020	Exterior Color	White Solid
Odometer	80 044 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	12/08/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 215/60/17 Summer 4.5 mm		Michelin 215/60/17 Summer 4.5 mm	
Bridgestone 215/60/17 Summer 4.5 mm		Bridgestone 215/60/17 Summer 3.5 mm	

Exterior

1		Part Position Damages Severity Repair mode	Door Front left Dent & Chips Diameter (mm) > 20 Repair
2		Part Position Damages Severity Repair mode	Step plate Front left Scratched - For info
4		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Repair
5		Part Position Damages Severity Repair mode	Step plate Back left Dent & Chips - For info
7		Part Position Damages Severity Repair mode	Tailgate / Boot door Back Scratched Length (cm) > 10 Repair
8		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair
11		Part Position Damages Severity Repair mode	Door Front right Dented Diameter (mm) > 20 Smart Repair
12		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Lumpsum repair

Interior damage

3		Part Position Damages Severity Repair mode	Interior cleaning Front Stained/dirty - Cleaning
6		Part Position Damages Severity Repair mode	Interior cleaning Back Stained/dirty - Cleaning
9		Part Position Damages Severity Repair mode	Interior tailgate lining Down Scratched - Replace
10		Part Position Damages Severity Repair mode	Interior tailgate lining Up Scratched - Replace