


Vehicle details

VIN	SJNFAAF16 U1049099	Brand	NISSAN	Maintenance date	-
Licence Plate	J7-55-FZ	Model	Juke DIG-T 117 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	24/07/2020	Year	2020	Exterior Color	White Solid
Odometer	73 552 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	29/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Hankook 215/60/17 Summer 6.5 mm		Hankook 215/60/17 Summer 6.5 mm	
Bridgestone 215/60/17 Summer 5.5 mm		Bridgestone 215/60/17 Summer 5.5 mm	

Exterior

1



Part

Alloy wheel 17"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

2



Part

Door

Position

Back left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

●

6



Part

Door

Position

Front right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

●

7



Part

Wing

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

Others

3

A close-up photograph of the back wiper arm of a car. A green arrow points to the wiper arm. Below the image are two green dots.


Part	Wiper arm
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace

4

A close-up photograph of the back wiper blade of a car. A green arrow points to the wiper blade. Below the image are two green dots.

Part	Wiper blade
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace

5

A close-up photograph of the back wiper blade cover of a car. A green arrow points to the wiper blade cover. Below the image are two green dots.

Part	Wiper blade cover
Position	Back
Damages	Missing
Severity	-
Repair mode	Replace