


Vehicle details

VIN	SJNFAAF16 U1049923	Brand	NISSAN	Maintenance date	-
Licence Plate	J7-84-GD	Model	Juke DIG-T 117 ActieAuto 5d N-Connecta APL	Maintenance mileage	-
Registration date	24/07/2020	Year	2020	Exterior Color	White Solid
Odometer	70 485 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	31/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Tow	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

<p>1</p>  <p>● ● ● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>3</p>  <p>● ●</p>	<table border="0"> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Chemical deposit</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Roof	Position	-	Damages	Chemical deposit	Severity	-	Repair mode	Lumpsum repair
Part	Door																						
Position	Front left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Roof																						
Position	-																						
Damages	Chemical deposit																						
Severity	-																						
Repair mode	Lumpsum repair																						

Interior damage

<p>2</p>  <p>● ● ●</p>	<table border="0"> <tr><td>Part</td><td>Interior cleaning</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Stained/dirty</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Cleaning</td></tr> </table>	Part	Interior cleaning	Position	Front right	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning										
Position	Front right										
Damages	Stained/dirty										
Severity	-										
Repair mode	Cleaning										