

Vehicle details

VIN	SJNFAAF16 U1050419	Brand	NISSAN	Maintenance date	-
Licence Plate	J5-87-FV	Model	Juke DIG-T 117 ActieAuto 5d Acenta APL	Maintenance mileage	-
Registration date	29/07/2020	Year	2020	Exterior Color	White Solid
Odometer	82 566 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	07/08/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Bridgestone 215/60/17 Summer 5.0 mm



Bridgestone 215/60/17 Summer 5.5 mm



Bridgestone 215/60/17 Summer 3.0 mm

Bridgestone 215/60/17 Summer 3.5 mm

Exterior

1



●●

Part	Lower bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



●●●

Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



●●●

Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



●●

Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

Others

3		<table><tr><td>Part</td><td>Wiper blade</td></tr><tr><td>Position</td><td>Back</td></tr><tr><td>Damages</td><td>Missing</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Wiper blade	Position	Back	Damages	Missing	Severity	-	Repair mode	Replace	4		<table><tr><td>Part</td><td>Wiper arm</td></tr><tr><td>Position</td><td>Back</td></tr><tr><td>Damages</td><td>Missing</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Wiper arm	Position	Back	Damages	Missing	Severity	-	Repair mode	Replace
Part	Wiper blade																								
Position	Back																								
Damages	Missing																								
Severity	-																								
Repair mode	Replace																								
Part	Wiper arm																								
Position	Back																								
Damages	Missing																								
Severity	-																								
Repair mode	Replace																								
5		<table><tr><td>Part</td><td>Wiper blade cover</td></tr><tr><td>Position</td><td>Back</td></tr><tr><td>Damages</td><td>Missing</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Wiper blade cover	Position	Back	Damages	Missing	Severity	-	Repair mode	Replace													
Part	Wiper blade cover																								
Position	Back																								
Damages	Missing																								
Severity	-																								
Repair mode	Replace																								