



NISSAN Qashqai

Qashqai 1.6

VIN NO SJNFAAJ10U2479411

Registration Number 10U2479411



MOT Date

2025-12-01

Last Service

2022-12-13

Number of Owners

2

Last Service Mileage

108091

Number of Keys

2

First Registration Date

2012-03-22

Odometer Reading

125996 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925053137
Inspection Date / Place	2025-09-25 / HARTMANN Compound-Professionals GmbH Dorfmark	Cosmetic Grade	5


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1598
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	144
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Airbag Status	Anti-lock braking	Cruise control
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Sunroof
Electrically folding wing mirrors	Radio	360°camera	Alloys wheels
Auxiliary Socket	Front parking sensors	Remote central locking	Roof rails
Stability control	Central locking	Leather steering wheel	Rear parking sensors


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Sunroof Type	Fixed Panoramic		


Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	5


23 Damages




4 Damages

6/14 - Report Number P20250925053137

13	Fuel Door / Back Right	Paint / Scratch / Scuff
14	Rim / Back Right	Out of Bodywork / Scratch
15	Bumper / Back	Paint / Scratch / Scuff
16	Tailgate	Paint / Scratch / Scuff
17	Rear Window / Back	Glass Break / Scratch / Scratch
18	Door / Back Left	Paint / Corrosion
19	Door / Back Left	Paint / Scratch / Scuff
20	Door / Front Left	Paint / Scratch / Scuff
21	Wing Expander / Front Left	Paint / Scratch / Scuff
22	Rim / Front Left	Out of Bodywork / Scratch
23	Corner Bumper / Front Left	Paint / Scratch / Scuff
24	Seat / Front Left	Interior / Dirty
25	Center Console	Interior / Dirty
26	Seat / Back Right	Interior / Dirty
27	Seat / Front Right	Interior / Dirty




1. Hood
Paint / Stone Chip -




2. Door / Back Left
Bodywork / Poor Previous Repair -



3. Door / Front Left
Paint / Poor Previous Repair -



4. Fender / Front Right
Paint / Scratch / Scuff -




5. Fender / Front Right
Paint / Scratch / Scuff -




6. Rim / Front Right
Out of Bodywork / Scratch -



7. Door / Front Right
Paint / Scratch / Scuff -




8. Door / Front Right
Paint / Scratch / Scuff -



9. Door / Back Right
Paint / Scratch / Line -



10. Door / Back Right
Bodywork / Dent / Dent -



11. Door / Back Right
Paint / Stone Chip -



12. Roof
Paint / Scratch / Scuff -




13. Fuel Door / Back Right
Paint / Scratch / Scuff -



14. Rim / Back Right
Out of Bodywork / Scratch -



15. Bumper / Back
Paint / Scratch / Scuff -



16. Tailgate
Paint / Scratch / Scuff -



17. Rear Window / Back
Glass Break / Scratch / Scratch -



18. Door / Back Left
Paint / Corrosion -



19. Door / Back Left
Paint / Scratch / Scuff -



20. Door / Front Left
Paint / Scratch / Scuff -



21. Wing Expander / Front Left
Paint / Scratch / Scuff -



22. Rim / Front Left
Out of Bodywork / Scratch -



23. Corner Bumper / Front Left
Paint / Scratch / Scuff -




24. Seat / Front Left
Interior / Dirty -



25. Center Console
Interior / Dirty -



26. Seat / Back Right
Interior / Dirty -



27. Seat / Front Right
Interior / Dirty -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Service Light	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	!	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	⚠	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)