

Inspection Protocol



NISSAN QASHQAI 1.6

Vehicle information

License plate	LXO260	Inspected by	C.C.
Year model	2012	Date of inspection	2025-06-26
Manuf. year/month	2012-10	City	Björkvik
First day in traffic	2012-10	Keys	2
Colour	Grå	Service book	Ja
Mileage	145 110 km	Latest service	2024-12-16
Fuel	Bensin	Mileage at the latest service	138 300 km
Transmission	Manuell	Summer tires	17" alu-fälg 4/4/5/5
Engine effect	86 kW	Winter tires	alu-fälg odubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Door, Front left	Scratches below 30 mm		60 €
Door, Rear left	Dings		-
Wing, Rear left	Scratches 30-100 mm		80 €
Bumper, Rear	Repor, 3-10 cm		80 €
Door, Rear right	Dings		-
Door, Front right	Scratches 30-100 mm		80 €
Bumper, Front	Scratches below 30 mm		60 €

Total excl. VAT	360 €
-----------------	-------

Service occasions

2000-MIL, 3000-MIL, 5500-MIL, 6500-MIL, 10000-MIL, 12000-MIL, 14000-MIL

Images

[See all images in large format](#)











[illegible]





Dörr Vänster fram Repor under 3 cm 800 kr





Dörr Vänster bak Dörruppslag



Skärm Vänster bak Repor 3-10 cm 1 100 kr



Stötfångare Bak Repor, 3-10 cm 1 100 kr





Dörr Höger bak Dörruppslag





Dörr Höger fram Repor 3-10 cm 1 100 kr



Stötfångare Fram Repor under 3 cm 800 kr



