

Vehicle details

VIN	SJNFAAZE1 U0087004	Brand	NISSAN	Maintenance date	-
Licence Plate	J9-24-BX	Model	Leaf ActieAuto 40kWh 5d Acenta APL	Maintenance mileage	-
Registration date	07/07/2020	Year	2020	Exterior Color	White Solid
Odometer	90 318 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

Spare key	✗
User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

2



Part	Alloy wheel 16"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

3




Part	Step plate
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

5




Part	Alloy wheel 16"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

6



Part	Bonnet
Position	Front
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

4



Part	Seat
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning