


Vehicle details

VIN	SJNFAAZE1 U0099459	Brand	NISSAN	Maintenance date	-
Licence Plate	J5-99-HD	Model	Leaf ActieAuto 40kWh 5d N-Connecta APL	Maintenance mileage	-
Registration date	06/08/2020	Year	2020	Exterior Color	White Solid
Odometer	50 152 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	11/08/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Goodyear 215/50/17 Summer 3.5 mm



Goodyear 215/50/17 Summer 4.0 mm



Goodyear 215/50/17 Summer 5.5 mm



Goodyear 215/50/17 Summer 5.0 mm



Exterior

1		Part: Door Position: Front left Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair	5		Part: Step plate Position: Back left Damages: Dent & Chips Severity: - Repair mode: For info
6		Part: Wing moulding Position: Back left Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	9		Part: Tailgate / Boot door Position: - Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair
10		Part: Wing Position: Back right Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair	11		Part: Bonnet Position: - Damages: Dented Severity: Diameter (mm) > 20 Repair mode: Smart Repair
12		Part: Roof Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair	13		Part: Roof post A/B/C Position: Left Damages: Dent & Chips Severity: Diameter (mm) > 20 Repair mode: Repair

Interior damage

2		Part: Carpet Position: Front left Damages: Perforated Severity: - Repair mode: For info	3		Part: Interior cleaning Position: Front Damages: Stained/dirty Severity: - Repair mode: Cleaning
4		Part: Interior cleaning Position: Back Damages: Stained/dirty Severity: - Repair mode: Cleaning	7		Part: Interior tailgate lining Position: Up Damages: Scratched Severity: - Repair mode: Replace
8		Part: Interior tailgate lining Position: Down Damages: Scratched Severity: - Repair mode: Replace			