



NISSAN Micra
Micra 1.2
VIN NO SJNFBAK12U2127878
Registration Number 12U2127878



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	4	1	111604 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2006-06-07	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20251001103435
Inspection Date / Place	2025-10-01 / ARS Altmann AG Riedstadt	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1198
Engine Size	1.2	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	115
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	CD Player	Airbag Status
Remote central locking	Radio		

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	14
Seat Heating	No		

Wheels & Tyres


Right Front Tyre Depth	4	Right Rear Tyre Depth	6
Left Rear Tyre Depth	6	Left Front Tyre Depth	4

Cosmetic Damage

28 Schäden



3 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Bumper / Front	Paint / Poor Previous Repair	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Bumper / Front	Paint / Scratch / Scuff	
6	Hubcap / Front Left	Out of Bodywork / Scratch	
7	Pillar / Front Left	Paint / Scratch / Scuff	
8	Roof	Paint / Scratch / Scuff	
9	Door / Back Left	Paint / Scratch / Scuff	
10	Door / Back Left	Bodywork / Dent / Dent	
11	Fender / Back Left	Bodywork / Dent / Dent	
12	Hubcap / Back Left	Out of Bodywork / Scratch	

13	Bumper / Back	Paint / Scratch / Scuff
14	Fender / Back Left	Bodywork / Dent / Dent
15	Fender / Back Left	Bodywork / Dent / Dent
16	Bumper / Back	Paint / Scratch / Scuff
17	Fender / Back Right	Paint / Scratch / Scuff
18	Fender / Back Right	Paint / Corrosion
19	Hubcap / Back Right	Out of Bodywork / Scratch
20	Door / Back Right	Bodywork / Dent / Dent
21	Fuel Door / Back Right	Bodywork / Dent / Dent
22	Panel Filling / Back Right	Interior / Scratched
23	Panel Filling / Front Right	Interior / Scratched
24	Door / Front Right	Paint / Scratch / Scuff
25	Door / Front Right	Bodywork / Dent / Dent
26	Hubcap / Front Right	Out of Bodywork / Scratch
27	Fender / Front Right	Paint / Poor Previous Repair
28	Fender / Back Right	Paint / Poor Previous Repair
29	Tailgate Upholstery / Back	Interior / Non - compliant



1. Hood
Bodywork / Dent / Dent -




2. Bumper / Front
Paint / Poor Previous Repair -



3. Bumper / Front
Paint / Scratch / Scuff -



4. Bumper / Front
Paint / Scratch / Scuff -




5. Bumper / Front
Paint / Scratch / Scuff -



6. Hubcap / Front Left
Out of Bodywork / Scratch -




7. Pillar / Front Left
Paint / Scratch / Scuff -




8. Roof
Paint / Scratch / Scuff -



9. Door / Back Left
Paint / Scratch / Scuff -



10. Door / Back Left
Bodywork / Dent / Dent -




11. Fender / Back Left
Bodywork / Dent / Dent -



12. Hubcap / Back Left
Out of Bodywork / Scratch -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Fender / Back Left
Bodywork / Dent / Dent -



15. Fender / Back Left
Bodywork / Dent / Dent -



16. Bumper / Back
Paint / Scratch / Scuff -




17. Fender / Back Right
Paint / Scratch / Scuff -




18. Fender / Back Right
Paint / Corrosion -



19. Hubcap / Back Right
Out of Bodywork / Scratch -



20. Door / Back Right
Bodywork / Dent / Dent -




21. Fuel Door / Back Right
Bodywork / Dent / Dent -




22. Panel Filling / Back Right
Interior / Scratched -



23. Panel Filling / Front Right
Interior / Scratched -



24. Door / Front Right
Paint / Scratch / Scuff -



25. Door / Front Right
Bodywork / Dent / Dent -




26. Hubcap / Front Right
Out of Bodywork / Scratch -



27. Fender / Front Right
Paint / Poor Previous Repair -



28. Fender / Back Right
Paint / Poor Previous Repair -



29. Tailgate Upholstery / Back
Interior / Non - compliant -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Brake			
Brake System Anomaly		✓	
Clutch			
Clutch Functioning		⚠	
General			
Test Driven Status		✓	

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)