



NISSAN Qashqai Diesel  
qashqai 1.5 dci Acenta

VIN NO SJNFCAJ10U1187791

Registration Number DN111MY



MOT Date

2023-12-15

Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date

2008-03-11

Odometer Reading

167609 km

Country First Registered

Italy

Inspection Report Summary

|                         |                       |                |                 |
|-------------------------|-----------------------|----------------|-----------------|
| Customer                | BCA Lodi              | Report Number  | P20251009105608 |
| Inspection Date / Place | 2025-10-09 / BCA Lodi | Cosmetic Grade | 5               |

Vehicle Summary


|                    |        |                        |        |
|--------------------|--------|------------------------|--------|
| Vehicle Condition  | Runner | VAT Type               | Margin |
| Fuel Type          | Diesel | Gearbox Type           | Manual |
| Colour             | Black  | Engine Size (cc)       | 1461   |
| Engine Size        | 1.5    | No of Doors            | 5      |
| Body Type          | SUV    | Drive Train            | Front  |
| Seat Colour        | Black  | No of Seats            | 5      |
| Seat Covering Name |        | Seat Covering          | Cloth  |
| Charging Cables    |        | NEDC CO2 Rating (q/km) | 139    |

Vehicle History & Documents

|                        |            |                      |    |
|------------------------|------------|----------------------|----|
| Service Book Available | -          | Next Service Mileage | km |
| Previous Usage         | Normal Use | Imported             | No |
| Manufacturer Warrenty  |            |                      |    |







Equipment

|                 |                        |                         |                               |
|-----------------|------------------------|-------------------------|-------------------------------|
| Central locking | Alloys wheels          | Volante multifuncion    | Remote adjusting wing mirrors |
| Cruise control  | Tyre Mobility Kit      | Power assisted steering | Digital Radio                 |
| Parcel Shef     | Remote central locking | Trip Computer           | Stability control             |


Wheels & Tyres

Mounted Tires


| Tyre / Wheel Type | Summer |                          |
|-------------------|--------|--------------------------|
|                   | FULDA  | 215/65//R16 - 98H / 1 mm |
|                   | FULDA  | 215/65//R16 - 98H / 1 mm |
|                   | NEXEN  | 215/65//R16 - 98H / 2 mm |
|                   | NEXEN  | 215/65//R16 - 98H / 2 mm |

Cosmetic Damage

28 Danni



14 Danni



46

3

| Component |                             | Damage                      | Comments |
|-----------|-----------------------------|-----------------------------|----------|
| 1         | Center Console              | Interior / Worn - out       |          |
| 2         | Other                       | Interior / Distorted        |          |
| 3         | Panel Filling / Front Left  | Interior / Broken           |          |
| 4         | Roof                        | Bodywork / Dent / Hail Area |          |
| 5         | Steering Wheel / Front      | Interior / Worn - out       |          |
| 6         | Bumper / Back               | Bodywork / Dent             |          |
| 7         | Panel Filling / Front Right | Interior / Broken           |          |
| 8         | Seat / Front Left           | Interior / Broken           |          |
| 9         | Door / Front Left           | Bodywork / Dent             |          |
| 10        | Door / Back Right           | Bodywork / Dent             |          |
| 11        | Panel Filling / Back Left   | Interior / Broken           |          |
| 12        | Mirror Shell / Front Right  | Bodywork / Breakage         |          |

|    |                            |                             |
|----|----------------------------|-----------------------------|
| 13 | Door / Front Right         | Bodywork / Dent             |
| 14 | Fender / Front Right       | Paint / Scratch / Line      |
| 15 | Mirror Shell / Front Left  | Paint / Scratch / Line      |
| 16 | Door / Back Left           | Bodywork / Dent             |
| 17 | Bumper / Front             | Bodywork / Dent             |
| 18 | Tailgate                   | Paint / Scratch / Line      |
| 19 | Fender / Back Left         | Paint / Scratch / Line      |
| 20 | Mirror Glass / Front Right | Glass Break                 |
| 21 | Other                      | Interior / Distorted        |
| 22 | Panel Filling / Back Right | Interior / Broken           |
| 23 | Fender / Front Left        | Paint / Scratch / Line      |
| 24 | Back Light / Right         | Glass Break / Scratch       |
| 25 | Hood                       | Bodywork / Dent             |
| 26 | Rim / Front Right          | Out of Bodywork / Scratch   |
| 27 | Pillar / Front Left        | Bodywork / Dent / Hail Area |
| 28 | Fender / Back Right        | Bodywork / Dent             |
| 29 | Bumper / Back              | Bodywork / Dent             |
| 30 | Wing Expander / Back Right | Paint / Scratch / Line      |
| 31 | Pillar / Front Right       | Bodywork / Dent / Hail Area |
| 32 | Rim / Front Left           | Out of Bodywork / Scratch   |
| 33 | Rim / Back Right           | Out of Bodywork / Scratch   |
| 34 | Other                      | Interior / Non - compliant  |
| 35 | Panel Filling / Back Left  | Interior / Broken           |
| 36 | Panel Filling / Back Right | Interior / Broken           |
| 37 | Roof Upholstery            | Interior / Ripped           |
| 38 | Windshield / Front         | Glass Break                 |
| 39 | Reflector / Back Right     | Bodywork / Breakage         |
| 40 | Dashboard / Front          | Interior / Warning Light ON |






1. Center Console  
Interior / Worn - out -



2.  
Interior / Distorted -



3. Panel Filling / Front Left  
Interior / Broken -



4. Roof  
Bodywork / Dent / Hail Area -



5. Steering Wheel / Front  
Interior / Worn - out -




6. Bumper / Back  
Bodywork / Dent -





7. Panel Filling / Front Right  
Interior / Broken -



8. Seat / Front Left  
Interior / Broken -



9. Door / Front Left  
Bodywork / Dent -



10. Door / Back Right  
Bodywork / Dent -



11. Panel Filling / Back Left  
Interior / Broken -



12. Mirror Shell / Front Right  
Bodywork / Breakage -






13. Door / Front Right  
Bodywork / Dent -



14. Fender / Front Right  
Paint / Scratch / Line -



15. Mirror Shell / Front Left  
Paint / Scratch / Line -



16. Door / Back Left  
Bodywork / Dent -



17. Bumper / Front  
Bodywork / Dent -



18. Tailgate  
Paint / Scratch / Line -





19. Fender / Back Left  
Paint / Scratch / Line -



20. Mirror Glass / Front Right  
Glass Break -




21.  
Interior / Distorted -



22. Panel Filling / Back Right  
Interior / Broken -




23. Fender / Front Left  
Paint / Scratch / Line -



24. Back Light / Right  
Glass Break / Scratch -






25. Hood  
Bodywork / Dent -



26. Rim / Front Right  
Out of Bodywork / Scratch -



27. Pillar / Front Left  
Bodywork / Dent / Hail Area -



28. Fender / Back Right  
Bodywork / Dent -



29. Bumper / Back  
Bodywork / Dent -



30. Wing Expander / Back Right  
Paint / Scratch / Line -





31. Pillar / Front Right  
Bodywork / Dent / Hail Area -



32. Rim / Front Left  
Out of Bodywork / Scratch -



33. Rim / Back Right  
Out of Bodywork / Scratch -



34.  
Interior / Non - compliant -



35. Panel Filling / Back Left  
Interior / Broken -



36. Panel Filling / Back Right  
Interior / Broken -





37. Roof Upholstery  
Interior / Ripped -



38. Windshield / Front  
Glass Break -



39. Reflector / Back Right  
Bodywork / Breakage -



40. Dashboard / Front  
Interior / Warning Light ON -

## Mechanical Condition

| Engine              |   |                     |   |
|---------------------|---|---------------------|---|
| Vehicle Start - up  | ✓ | Engine Starts       | ✓ |
| Engine Leak Visible | ✓ |                     |   |
| Clutch              |   |                     |   |
| Clutch Functioning  | ! |                     |   |
| Equipments Test     |   |                     |   |
| Other Equipments    | ✓ | AC / Heating System | ✓ |
| Levels              |   |                     |   |
| Brakes Fluid        | ✓ | Coolant Fluid       | ! |

## Test Drive Inspection

| Other Checks                                                                                  |   |                    |                    |
|-----------------------------------------------------------------------------------------------|---|--------------------|--------------------|
| Steering                                                                                      | ✓ | Brakes             | !                  |
| Suspension                                                                                    | ! |                    |                    |
| Gearbox                                                                                       |   |                    |                    |
| Manual Gearbox                                                                                | ✓ |                    |                    |
| General                                                                                       |   |                    |                    |
| Test Driven Status                                                                            | ✓ | Test Drive Comment | SPIA AIRBAG ACCESA |
| Equipments Test                                                                               |   |                    |                    |
| Steering   Noise / Anomaly                                                                    | ✓ |                    |                    |
| Engine                                                                                        |   |                    |                    |
| Power Loss                                                                                    | ✓ | Fume Quantity      | !                  |
| Engine Noise                                                                                  | ! |                    |                    |
| ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage |   |                    |                    |
| ! Damages or malfunction detected that requires repairs by the buyer                          |   |                    |                    |
| NA Not applicable                                                                             |   |                    |                    |
| ☐ Not tested                                                                                  |   |                    |                    |