



NISSAN Qashqai

Qashqai 1.6 dCi Xtronic

VIN NO SJNFDAJ11U1444213
Registration Number 11U1444213



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-10-01	1	2	213588 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-08-20	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250903103402
Inspection Date / Place	2025-09-03 / SULOJA Mönchengladbach	Cosmetic Grade	4

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1600
Engine Size	1.6	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	128
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	360°camera	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Diesel particulate filter	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Sunroof	Central locking
Electrically folding wing mirrors	Leather steering wheel	Radio	Rear parking sensors
USB Socket	Adaptivecruisecontrol	Alloys wheels	Auxiliary Socket
Cruise control	Front fog lamps	Highbeamassist	Remote central locking
Roof rails	Stability control	CD Player	Electrically adjustable seats
Laneassist	LED Headlamps	Rain sensitive windscreen wipers	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front
Sunroof Type	Fixed Panoramic		

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4

Cosmetic Damage

14 Schäden



1 Schäden



Component		Damage	Comments
1	Side Panel / Back Left	Bodywork / Dent / Dent	
2	Side Panel / Back Left	Paint / Scratch / Scuff	
3	Door / Back Left	Paint / Poor Previous Repair	
4	Door / Back Left	Paint / Scratch / Scuff	
5	Door / Front Left	Paint / Scratch / Scuff	
6	Hood	Paint / Stone Chip	
7	Bumper / Front	Paint / Stone Chip	
8	Door / Back Right	Paint / Scratch / Scuff	
9	Door / Front Right	Paint / Scratch / Scuff	
10	Side Panel / Back Right	Paint / Scratch / Scuff	
11	Tailgate	Paint / Scratch / Scuff	
12	Bumper / Back	Paint / Poor Previous Repair	


13	Bumper / Back	Paint / Scratch / Scuff
14	Pillar / Back Left	Bodywork / Dent / Dent
15	Seat / Front Left	Interior / Scratched




1. Side Panel / Back Left
Bodywork / Dent / Dent -



2. Side Panel / Back Left
Paint / Scratch / Scuff -



3. Door / Back Left
Paint / Poor Previous Repair -



4. Door / Back Left
Paint / Scratch / Scuff -



5. Door / Front Left
Paint / Scratch / Scuff -



6. Hood
Paint / Stone Chip -



7. Bumper / Front
Paint / Stone Chip -



8. Door / Back Right
Paint / Scratch / Scuff -



9. Door / Front Right
Paint / Scratch / Scuff -



10. Side Panel / Back Right
Paint / Scratch / Scuff -



11. Tailgate
Paint / Scratch / Scuff -




12. Bumper / Back
Paint / Poor Previous Repair -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Pillar / Back Left
Bodywork / Dent / Dent -



15. Seat / Front Left
Interior / Scratched -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		Not Performed	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)