



NISSAN Qashqai  
Qashqai 1.2 DIG-T

VIN NO SJNFEAJ11U1754069  
Registration Number 11U1754069



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	129127 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-01-10	115718	2016-09-26	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250826111638
Inspection Date / Place	2025-08-26 / ARS Altmann AG Wolnzach	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour		Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	129
Gearbox Type	Manual		


Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Trip Computer	Alloys wheels	Cruise control	Remote central locking
CD Player	Leather steering wheel	Airbag Status	Anti-lock braking
Remote adjusting wing mirrors	Stability control	Central locking	Radio

Equipment Details

Air Conditioning	Yes	Alloy Wheel Size	16
Seat Heating	No		


Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4




Cosmetic Damage

18 Schäden




1 Schäden




Component		Damage	Comments
1	Roof	Bodywork / Dent / Dent	
2	Roof	Bodywork / Dent / Dent	
3	Door / Back Right	Bodywork / Dent / Dent	
4	Wing Repeater / Left	Glass Break	
5	Pillar / Front Left	Bodywork / Dent / Dent	
6	Door / Front Left	Paint / Scratch / Scuff	
7	Pillar / Front Left	Bodywork / Dent / Dent	
8	Seat / Front Left	Interior / Scratched	
9	Door / Back Left	Paint / Scratch / Scuff	
10	Bumper / Back	Paint / Scratch / Scuff	
11	Bumper / Back	Paint / Scratch / Scuff	
12	Tailgate	Paint / Scratch / Scuff	
13	Rim / Back Right	Out of Bodywork / Scratch	

14	Pillar / Back Right	Bodywork / Dent / Dent
15	Door / Front Right	Paint / Scratch / Scuff
16	Mirror Shell / Front Right	Paint / Scratch / Scuff
17	Bumper / Front	Paint / Scratch / Scuff
18	Bumper / Front	Paint / Scratch / Scuff
19	Tailgate	Bodywork / Dent / Dent






1. Roof  
Bodywork / Dent / Dent -



2. Roof  
Bodywork / Dent / Dent -




3. Door / Back Right  
Bodywork / Dent / Dent -



4. Wing Repeater / Left  
Glass Break -



5. Pillar / Front Left  
Bodywork / Dent / Dent -



6. Door / Front Left  
Paint / Scratch / Scuff -





7. Pillar / Front Left  
Bodywork / Dent / Dent -



8. Seat / Front Left  
Interior / Scratched -




9. Door / Back Left  
Paint / Scratch / Scuff -



10. Bumper / Back  
Paint / Scratch / Scuff -



11. Bumper / Back  
Paint / Scratch / Scuff -



12. Tailgate  
Paint / Scratch / Scuff -






13. Rim / Back Right  
Out of Bodywork / Scratch -



14. Pillar / Back Right  
Bodywork / Dent / Dent -



15. Door / Front Right  
Paint / Scratch / Scuff -



16. Mirror Shell / Front Right  
Paint / Scratch / Scuff -



17. Bumper / Front  
Paint / Scratch / Scuff -



18. Bumper / Front  
Paint / Scratch / Scuff -



19. Tailgate  
Bodywork / Dent / Dent -



## Mechanical Condition

### Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)