



NISSAN Qashqai  
Qashqai 1.2 DIG-T

VIN NO SJNFEAJ11U1754069  
Registration Number 11U1754069



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| -            | 2                    | 2                       | 129127 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| 2024-01-10   | 115718               | 2016-09-26              | -                        |

Inspection Report Summary

|                         |                                         |                |                 |
|-------------------------|-----------------------------------------|----------------|-----------------|
| Customer                | BCA Online                              | Report Number  | P20250826111638 |
| Inspection Date / Place | 2025-08-26 / ARS Altmann<br>AG Wolnzach | Cosmetic Grade | 5               |

Vehicle Summary


|                    |        |                        |        |
|--------------------|--------|------------------------|--------|
| Vehicle Condition  | Runner | VAT Type               | Margin |
| Fuel Type          | Petrol | Road Worthy            | Yes    |
| Colour             |        | Engine Size (cc)       | 1197   |
| Engine Size        | 1.2    | No of Doors            | 5      |
| Body Type          | SUV    | Drive Train            | Front  |
| Seat Colour        |        | No of Seats            | 5      |
| Seat Covering Name |        | Seat Covering          | Cloth  |
| Charging Cables    |        | NEDC CO2 Rating (q/km) | 129    |
| Gearbox Type       | Manual |                        |        |

Vehicle History & Documents

|                        |         |                      |    |
|------------------------|---------|----------------------|----|
| Service Book Available | Present | Next Service Mileage | km |
| Previous Usage         |         | Imported             | No |
| Manufacturer Warrenty  |         |                      |    |







Equipment

|                               |                        |                 |                        |
|-------------------------------|------------------------|-----------------|------------------------|
| Trip Computer                 | Alloys wheels          | Cruise control  | Remote central locking |
| CD Player                     | Leather steering wheel | Airbag Status   | Anti-lock braking      |
| Remote adjusting wing mirrors | Stability control      | Central locking | Radio                  |

Equipment Details


|                  |     |                  |    |
|------------------|-----|------------------|----|
| Air Conditioning | Yes | Alloy Wheel Size | 16 |
| Seat Heating     | No  |                  |    |

Wheels & Tyres


|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 4 |
| Right Rear Tyre Depth  | 4 | Left Rear Tyre Depth  | 4 |

Cosmetic Damage

18 Schäden




1 Schäden




| Component |                      | Damage                    | Comments |
|-----------|----------------------|---------------------------|----------|
| 1         | Roof                 | Bodywork / Dent / Dent    |          |
| 2         | Roof                 | Bodywork / Dent / Dent    |          |
| 3         | Door / Back Right    | Bodywork / Dent / Dent    |          |
| 4         | Wing Repeater / Left | Glass Break               |          |
| 5         | Pillar / Front Left  | Bodywork / Dent / Dent    |          |
| 6         | Door / Front Left    | Paint / Scratch / Scuff   |          |
| 7         | Pillar / Front Left  | Bodywork / Dent / Dent    |          |
| 8         | Seat / Front Left    | Interior / Scratched      |          |
| 9         | Door / Back Left     | Paint / Scratch / Scuff   |          |
| 10        | Bumper / Back        | Paint / Scratch / Scuff   |          |
| 11        | Bumper / Back        | Paint / Scratch / Scuff   |          |
| 12        | Tailgate             | Paint / Scratch / Scuff   |          |
| 13        | Rim / Back Right     | Out of Bodywork / Scratch |          |


|    |                            |                         |
|----|----------------------------|-------------------------|
| 14 | Pillar / Back Right        | Bodywork / Dent / Dent  |
| 15 | Door / Front Right         | Paint / Scratch / Scuff |
| 16 | Mirror Shell / Front Right | Paint / Scratch / Scuff |
| 17 | Bumper / Front             | Paint / Scratch / Scuff |
| 18 | Bumper / Front             | Paint / Scratch / Scuff |
| 19 | Tailgate                   | Bodywork / Dent / Dent  |



1. Roof  
Bodywork / Dent / Dent -



2. Roof  
Bodywork / Dent / Dent -




3. Door / Back Right  
Bodywork / Dent / Dent -



4. Wing Repeater / Left  
Glass Break -



5. Pillar / Front Left  
Bodywork / Dent / Dent -




6. Door / Front Left  
Paint / Scratch / Scuff -



7. Pillar / Front Left  
Bodywork / Dent / Dent -



8. Seat / Front Left  
Interior / Scratched -



9. Door / Back Left  
Paint / Scratch / Scuff -



10. Bumper / Back  
Paint / Scratch / Scuff -



11. Bumper / Back  
Paint / Scratch / Scuff -




12. Tailgate  
Paint / Scratch / Scuff -



13. Rim / Back Right  
Out of Bodywork / Scratch -



14. Pillar / Back Right  
Bodywork / Dent / Dent -



15. Door / Front Right  
Paint / Scratch / Scuff -



16. Mirror Shell / Front Right  
Paint / Scratch / Scuff -



17. Bumper / Front  
Paint / Scratch / Scuff -



18. Bumper / Front  
Paint / Scratch / Scuff -



19. Tailgate  
Bodywork / Dent / Dent -

## Mechanical Condition

### Control Lights

|                                              |   |                                 |   |
|----------------------------------------------|---|---------------------------------|---|
| Display Defect                               | ✓ | ABS Warning Light               | ✓ |
| ESP Fault/Traction Control Malfunction Light | ✓ | Airbag Warning Light            | ✓ |
| Oil Pressure Warning Light                   | ✓ | Brake Warning Light             | ✓ |
| Power Steering Warning Light                 | ✓ | Alternator / Battery            | ✓ |
| No Dashboard Lights                          | ✓ | Tire Pressure Monitoring System | ✓ |

### Equipments Test

|                     |   |                               |   |
|---------------------|---|-------------------------------|---|
| Central Locking     | ✓ | Main & Spare Keys Functioning | ✓ |
| Electric Windows    | ✓ | Audio Equipment               | ✓ |
| AC / Heating System | ✓ |                               |   |

### Engine

|                     |   |                     |   |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ✓ |
| Engine Starts       | ✓ |                     |   |

### Gearbox

|          |   |
|----------|---|
| Gear Box | ✓ |
|----------|---|

### Levels

|              |   |               |   |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)