



HYUNDAI i30

i30cw 1.6 CRDi blue

VIN NO TMADB81SABJ039687
Registration Number SABJ039687



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250910135404
Inspection Date / Place	2025-09-10 / BCA Neuss	Cosmetic Grade	5


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	No
Colour	Black	Engine Size (cc)	1582
Engine Size	1.6	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Grau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	122
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			








Equipment

Airbag Status	Anti-lock braking	Remote adjusting wing mirrors	Stability control
Leather steering wheel	Rear parking sensors	Alloys wheels	Diesel particulate filter
Remote central locking	CD Player	Radio	


Equipment Details

Air Conditioning	Climate Control	Alloy Wheel Size	15
------------------	-----------------	------------------	----

27 Schäden



2 Schäden

6/14 - Report Number P20250910135404

13	Door / Front Left	Bodywork / Dent / Dent
14	Door / Back Left	Paint / Scratch / Scuff
15	Rocker Panel / Center Left	Bodywork / Dent / Dent
16	Rocker Panel / Center Left	Bodywork / Dent / Dent
17	Rear Window Joint / Back	Bodywork / Breakage / Crack
18	Center Console	Interior / Broken
19	Luggage Space Cover / Back	Interior / Missing
20	Fender / Back Right	Bodywork / Dent / Dent
21	Fender / Back Right	Paint / Scratch / Scuff
22	Door / Back Right	Paint / Scratch / Scuff
23	Door / Front Right	Paint / Scratch / Scuff
24	Door / Front Right	Paint / Scratch / Scuff
25	Mirror / Front Right	Paint / Scratch / Scuff
26	Bumper / Back	Paint / Scratch / Scuff
27	Bumper / Back	Paint / Scratch / Scuff
28	Bumper / Back	Bodywork / Breakage / Crack
29	Bumper / Back	Paint / Poor Previous Repair



1. Door / Front Left
Paint / Poor Previous Repair -




2. Door Joint / Front Left Bottom
Bodywork / Breakage / Crack -



3. Fender / Back Left
Paint / Poor Previous Repair -



4. Fender / Back Right
Paint / Poor Previous Repair -




5. Door / Front Right
Paint / Poor Previous Repair -



6. Corner Bumper / Front Right
Bodywork / Breakage / Crack -




7. Front Light / Front Right
Glass Break -




8. Bumper / Front
Paint / Scratch / Scuff -



9. Front Light / Front Left
Glass Break -




10. Hood
Bodywork / Dent / Dent -




11. Wing Repeater / Left
Bodywork / Dent / Dent -




12. Wing Repeater / Left
Bodywork / Dent / Dent -



13. Door / Front Left
Bodywork / Dent / Dent -



14. Door / Back Left
Paint / Scratch / Scuff -



15. Rocker Panel / Center Left
Bodywork / Dent / Dent -



16. Rocker Panel / Center Left
Bodywork / Dent / Dent -



17. Rear Window Joint / Back Bodywork / Breakage / Crack -



18. Center Console
Interior / Broken -



19. Luggage Space Cover / Back Interior / Missing -



20. Fender / Back Right Bodywork / Dent / Dent -



21. Fender / Back Right Paint / Scratch / Scuff -



22. Door / Back Right Paint / Scratch / Scuff -



23. Door / Front Right Paint / Scratch / Scuff -



24. Door / Front Right Paint / Scratch / Scuff -



25. Mirror / Front Right
Paint / Scratch / Scuff -



26. Bumper / Back
Paint / Scratch / Scuff -



27. Bumper / Back
Paint / Scratch / Scuff -



28. Bumper / Back
Bodywork / Breakage / Crack -



29. Bumper / Back
Paint / Poor Previous Repair -

Mechanical Condition

Control Lights

Display Defect	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	⚠	No Dashboard Lights	⚠
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Equipments Test

Electric Windows	✓	Audio Equipment	✓
------------------	---	-----------------	---

Levels

Coolant Fluid	✓	Brakes Fluid	✓
---------------	---	--------------	---

Test Drive Inspection

Steering Wheel

Steering Noise / Anomaly	⚠
----------------------------	---

Clutch

Clutch Functioning	✓
--------------------	---

Engine

Fume Quantity	✓	Power Loss	✓
---------------	---	------------	---

Brake

Brake System Anomaly	✓
----------------------	---

General

Test Driven Status	✓
--------------------	---

✓ **No troubles detected, good condition or correct tests, according to vehicle age and mileage**

⚠ **Damages or malfunction detected that requires repairs by the buyer**

 *Not applicable*

 *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)