



Hyundai Tucson: L639VB

Vinnumber:	TMAJB811BMJ041540	Versionname:	Tucson 1.6 T-GDI 169kW HEV N Line Sky Smart automaat
First Registrationdate:	18/10/2021	Fiscalpower:	
Expertise Mileage:	101477	Power Kw:	169
Bodytype:		Body colour	Phantom Black mica
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Hybrid Petrol	Parking lot	586
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Lining Alcantara
Windows electric F		Sun Roof electric
Radio multimedia		Panoramic roof
		Central consol F
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 50 / 19 / 103 / Y / Aluminium	6,3 mm	Bridgestone	Summer
	Right	235 / 50 / 19 / 103 / Y / Aluminium	6,4 mm	Bridgestone	Summer
Rear	Left	235 / 50 / 19 / 103 / Y / Aluminium	7,2 mm	Bridgestone	Summer
	Right	235 / 50 / 19 / 103 / Y / Aluminium	7,8 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

User's manual, Missing, Replace

No pictures to display

Interior, Dirty, Cleaning



Outer backrest protection R, Scratch(es), Replace



Door FL, Scratch(es), Repair and paint (complete)



Outer door handle FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)



Bumper F, Bad repair, Repair and paint (complete)



Bonnet, Chemical polution, Polish



Hub cap RR, Missing, Replace

[Damage Picture - 1](#)

Wing RR, Dent(s), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Tow bar (removable), Missing, Replace



Luggage compartment cover, Missing, Replace



Spare wheel, Deformed / Strained, Replace



Bumper corner RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Sunroof (electric), Scratch(es), Replace

