


Vehicle details

VIN	TMAJD811B NJ113769	Brand	HYUNDAI	Maintenance date	-
Licence Plate	R0-87-DF	Model	TUCSON 1.6 T-GDI HEV Comfort Automaat 5d	Maintenance mileage	-
Registration date	05/08/2022	Year	2022	Exterior Color	White Solid
Odometer	198 858 km	Engine size	1598	interior Color	Black
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	02/06/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Tow	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/65/17 Summer 6.0 mm		Michelin 215/65/17 Summer 6.0 mm	
Michelin 215/65/17 Summer 5.0 mm		Michelin 215/65/17 Summer 5.0 mm	


Exterior

1



Part	Wing
Position	Front left
Damages	Rusty
Severity	Diameter (mm) > 4
Repair mode	Repair

5



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning




3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning



4



Part	Other interior
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning



gerookt in voertuig

Others

6



Part	Damage appraisal
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info